



# basic education

---

Department:  
Basic Education  
**REPUBLIC OF SOUTH AFRICA**

## **SENIOR CERTIFICATE EXAMINATIONS/ NATIONAL SENIOR CERTIFICATE EXAMINATIONS**

**MECHANICAL TECHNOLOGY: WELDING AND METALWORK**

**MAY/JUNE 2024**

**MARKING GUIDELINES**

**MARKS: 200**

**These marking guidelines consist of 17 pages.**

**QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)**

- |     |     |            |
|-----|-----|------------|
| 1.1 | A ✓ | (1)        |
| 1.2 | B ✓ | (1)        |
| 1.3 | A ✓ | (1)        |
| 1.4 | D ✓ | (1)        |
| 1.5 | C ✓ | (1)        |
| 1.6 | C ✓ | (1)        |
|     |     | <b>[6]</b> |

**QUESTION 2: SAFETY (GENERIC)**

2.1 **First aid:**

- When illness occurs. ✓
- When an injury is sustained. ✓
- When an accident occurs. ✓

(Any 2 x 1) (2)

2.2 **Bench grinder:**

- A. A fire extinguisher should be available. ✓
- B. Safety glasses must be worn. ✓
- C. Maximum grinding wheel speed. ✓
- D. Maximum distance between tool rest and grinding wheel. ✓

(4)

2.3 **Drill press:**

- Never try to stop/hold the work piece by hands when the drill bit get stuck during drilling. ✓
- Don't force a drill bit into the work piece. ✓
- Keep loose clothing and hair away from revolving parts. ✓
- Never leave the machine running if it is unattended. ✓
- Use a brush or wooden rod to remove chips from the drill. ✓
- Do not put hands near moving parts. ✓
- Never clean or adjust the machine while it is in motion. ✓
- Never try to stop the drill/chuck by hands. ✓

(Any 2 x 1) (2)

2.4 **Surface grinder:**

- Never clean or adjust the machine while it is in motion. ✓
- Know how to stop the machine in an emergency. ✓
- Do not use excessive force when grinding the work piece. ✓
- Immediately report any dangerous defects of the machine. ✓
- Stop using defective machinery until it has been repaired by a qualified person. ✓
- Ensure that the grinding wheel is not submerged in coolant. ✓
- Never leave the machine running if it is unattended. ✓
- Do not put hands near moving parts. ✓

(Any 2 x 1) (2)

[10]

**QUESTION 3: MATERIALS (GENERIC)**

**3.1 Critical temperature:**

3.1.1 **Hardening:**  
Above ✓ (1)

3.1.2 **Tempering:**  
Below ✓ (1)

3.1.3 **Normalising:**  
Above ✓ (1)

**3.2 Machining test:**

- The chips heating colour ✓
- The chips curl ✓ (2)

**3.3 Material tests:**

- Sound test ✓
  - Bending test ✓
  - Filing test ✓
  - Hardness test ✓
  - Density test ✓
  - Weight measurement ✓
  - Magnetic test ✓
  - Visual inspection/observation ✓
  - Scratch test ✓
- (Any 3 x 1) (3)

**3.4 Quenching methods:**

- Carburising ✓
  - Nitriding ✓
  - Cyaniding ✓
- (Any 2 x 1) (2)

**3.5 Heat treatment temperature:**

- Pyrometer ✓
  - Crayons ✓
  - Visually ✓
  - Magnet ✓
- (Any 1 x 1) (1)

**3.6 Heat-treatment steps:**

- Heat the metal. ✓
- Soak the metal. ✓
- Cool the metal. ✓ (3)

**[14]**

**QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)**

- |      |     |             |
|------|-----|-------------|
| 4.1  | D ✓ | (1)         |
| 4.2  | B ✓ | (1)         |
| 4.3  | B ✓ | (1)         |
| 4.4  | A ✓ | (1)         |
| 4.5  | D ✓ | (1)         |
| 4.6  | A ✓ | (1)         |
| 4.7  | C ✓ | (1)         |
| 4.8  | B ✓ | (1)         |
| 4.9  | D ✓ | (1)         |
| 4.10 | A ✓ | (1)         |
| 4.11 | C ✓ | (1)         |
| 4.12 | C ✓ | (1)         |
| 4.13 | B ✓ | (1)         |
| 4.14 | D ✓ | (1)         |
|      |     | <b>[14]</b> |

**QUESTION 5: TERMINOLOGY(TEMPLATES) (SPECIFIC)**

**5.1 Labeling of roof truss:**

- A - Roof sheeting ✓
- B - Ridging ✓
- C - King post ✓
- D - Tie beam/main tie ✓
- E - Internal bracing ✓
- F - Rafter ✓
- G - Gusset plate ✓

(7)

**5.2 Brass ring calculations:**


5.2.1 Mean $\varnothing$  = Outside $\varnothing$  – plate thickness  
= 380 – 15 ✓  
= 365 mm ✓

(2)

5.2.2 Mean circumference =  $\pi \times$  Mean $\varnothing$   
=  $\pi \times 365$  ✓  
= 1146,68 ✓  
= 1147 mm ✓

(3)

**5.3 Weld symbol:**



(4)

**5.4 Supplementary weld symbols:**

- Indicate additional ✓ information about a weld. ✓
- Supplementary ✓ information about a weld. ✓

(Any 1 x 2) (2)

**5.5 Advantages of using templates:**

- Quicker to use to improve mass production. ✓
- Accurate production. ✓
- Cheap to manufacture. ✓
- Unskilled labour will be able to use it. ✓
- Avoid unnecessary wastages / cost effective. ✓
- It gives uniformity in production. ✓
- Can be reused. ✓

(Any 2 x 1) (2)

5.6 **Template machine tools:**

- Planer ✓
- Circular saw ✓
- Drilling machine ✓
- Jig saw ✓
- Sanding machine ✓
- Shears ✓
- Cut off saw ✓
- Bench grinder ✓
- Hydraulic press ✓

**(Any 3 x 1)** (3)

**[23]**

## QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)

### 6.1 Working principles:

#### 6.1.1 Power driven guillotine:

- Activated by foot pedal. ✓
  - Driven by an electric motor, flywheel, gearbox and axle. ✓
  - Top cutting blade moves downwards. ✓
  - Uses eccentric motion for the cutting stroke. ✓
- (4)

#### 6.1.2 Pyramid bending rolls:

- A bending roll has three rollers mounted in a horizontal position. ✓
  - At the bottom there are two fixed rollers next to each other, rotating in unison. ✓
  - The top roller is adjustable (up and down) applying downward pressure on the metal. ✓
  - That causes the metal to deflect and ultimately form the round shape desired. ✓
- (4)

### 6.2 Uses of the hydraulic press:

- Installing components. ✓
- Removing components. ✓
- To press profiles. ✓
- Bending. ✓

(Any 2 x 1) (2)

### 6.3. Types of hardness testers:

- Rockwell Hardness tester ✓
- Brinell Hardness tester ✓
- Vickers Hardness tester ✓

(Any 2 x 1) (2)

### 6.4 Labels for gas welding:

- A – Filler rod/Welding rod/Brazing rod ✓
  - B – Welding tip/Welding nozzle ✓
  - C – Flame ✓
  - D – Parent metal/Work piece ✓
- (4)

### 6.5 Function of the plasma cutter:

- Cuts ✓ through electrically conductive materials. ✓
- (2)

[18]



## QUESTION 7: FORCES (SPECIFIC)

### 7.1 Beams:

7.1.1 **Distributed load:**  
 $10 \times 3 = 30 \text{ N} \checkmark$  (1)

7.1.2 **Reaction (RL):**  
**Take moments about RR:**  
 $RL \times 10 = (25 \times 2) + (30 \times 6,5) + (15 \times 8)$   
 $= 50 + 195 + 120$

$$\therefore \frac{10 \text{ RL}}{10} = \frac{365}{10}$$
$$RL = 36,5 \text{ N} \checkmark$$

**Reaction (RR):**  
**Take moments about RL:**  
 $RR \times 10 = (15 \times 2) + (30 \times 3,5) + (25 \times 8)$   
 $= 30 + 105 + 200$

$$\therefore \frac{10 \text{ RR}}{10} = \frac{335}{10}$$
$$RR = 33,5 \text{ N} \checkmark$$
 (8)

7.1.3 **Shear force:**


$$SF_A = 36,5 - 15 \checkmark$$
$$= 21,5 \text{ N} \checkmark$$

$$SF_B = 36,5 - 15 - 30 \checkmark$$
$$= -8,5 \text{ N} \checkmark$$

$$SF_C = 36,5 - 15 - 30 - 25 \checkmark$$
$$= -33,5 \text{ N} \checkmark$$
 (6)

7.1.4 **Scale:**

Space diagram 1 m = 10 mm  
Shear force 1N = 1 mm



**Note to marker:**  
Marker must redraw the shear force diagram according to given scales for marking purposes.

(8)

## 7.2 Stress and Strain:

### 7.2.1 Stress:

$$\begin{aligned} A &= \frac{\pi D^2}{4} \\ &= \frac{\pi \times 0,036^2}{4} \checkmark \\ &= 1,01787602 \times 10^{-3} \text{m}^2 \checkmark \end{aligned}$$

$$\begin{aligned} \text{Stress} &= \frac{F}{A} \\ &= \frac{110 \times 10^3}{1,01787602 \times 10^{-3}} \checkmark \\ &= 108068171,2 \text{ Pa} \\ &= 108,07 \text{ MPa} \checkmark \end{aligned}$$

(5)


### 7.2.2 Strain:

$$\begin{aligned} \varepsilon &= \frac{\Delta L}{OL} \\ &= \frac{0,6}{125} \checkmark \\ &= 0,0048 \checkmark \end{aligned}$$

(3)

7.3 Simple frame:


7.3.1 Space diagram:



**NOTE:** Draw to scale on transparency for marking purpose. Mark allocation for scale and each member with arrows showing strut or tie.

(4)

7.3.2 Force diagram:



**Note to marker:**  
 Marker must redraw the space and force diagrams according to given scales for marking purposes.

(4)

7.3.3 Magnitude and nature of force:

Member	Force	Nature
AD	100 N ✓	Strut ✓
BD	174 N ✓	Strut ✓
CD	86 N ✓	Tie ✓

**NOTE:** Allow ± 2 mm tolerance.

(6)  
 [45]

**QUESTION 8: JOINING METHODS (INSPECTION OF WELD) (SPECIFIC)**

**8.1 Prevent incomplete penetration:**

- Use correct travel speed. ✓
- Use narrow/correct joint. ✓
- Use correct welding current. ✓
- Use correct electrode angle. ✓
- Use correct weaving technique. ✓
- Clean the base/parent metal. ✓

(Any 3 x 1) (3)

**8.2 Visual inspection of welds:**

- Cracks ✓
- Lack of fusion ✓
- Excessive spatter ✓
- Undercutting. ✓
- Craters ✓

(Any 2 x 1) (2)

**8.3 Fusion:**

The proper bonding of the weld metal ✓ with the base metal. ✓

(2)

**8.4 Undercutting:**

- Adjust the welding parameters. ✓
- Control heat input. ✓
- Ensure proper electrode angle. ✓

(3)

**8.5 Purpose of the nick break test:**

- To assess the ductility. ✓
- To check penetration. ✓
- To check for fusion. ✓
- To check porosity. ✓
- To check for undercutting. ✓

(Any 2 x 1) (2)

**8.6 Width and height of a weld bead:**

To provide structural integrity ✓ and proper strength ✓ distribution along the joint. ✓

(3)

**8.7 Inspection of welds:**

- Clean bead. ✓
- Constant width and height. ✓
- Fusion and penetration. ✓
- Absence of cracks. ✓
- Undercutting. ✓
- Craters ✓

(Any 3 x 1) (3)

8.8 **Liquid dye test on a welded joint:**

- Clean the surface to be tested. ✓
- Spray the liquid dye penetrant onto the surface and allow liquid dye to penetrate. ✓
- Remove excess dye with a cleaner. ✓
- Spray a developer onto the surface to bring out the colour. ✓
- Observe surface for defects. ✓

(5)  
**[23]**

**QUESTION 9: JOINING METHODS (STRESSES AND DISTORTION) (SPECIFIC)**

**9.1 Stress relieving:**

- To reduce/eliminate residual stresses in welded structures. ✓
- To improve their dimensional stability. ✓
- To improve resistance to distortion. ✓

(3)

**9.2 Factors contributing to distortion and residual stress:**

- Material properties. ✓
- Joint design. ✓
- Welding process. ✓
- Parameters. ✓
- Rate of cooling. ✓

(Any 3 x 1)

(3)

**9.3 Mechanical properties:**

- Hardness ✓
- Strength ✓
- Ductility ✓
- Malleability ✓
- Elasticity ✓

(Any 4 x 1)

(4)

**9.4 Factors influencing the grain size:**

- The amount of temperature and duration of the annealing process. ✓
- The composition of the steel. ✓
- Its melting point. ✓

(3)

**9.5 Cause of shrinkage:**

The cooling of the weld metal, which leads to contraction. ✓

(1)

**9.6 Welding methods:**

- Tack welding. ✓
- Intermittent welding. ✓
- Back-step welding. ✓
- Do not over weld. ✓
- Place welds near neutral axis. ✓
- Use as few passes as possible. ✓
- Anticipate shrinkage forces. ✓
- Use strongbacks. ✓
- Use clamps, jigs and fixtures. ✓

(Any 4 x 1)

(4)

[18]

**QUESTION 10: MAINTENANCE (SPECIFIC)**

10.1 **Failure in machines:**

- Lack of lubrication or incorrect lubrication. ✓
- Overloading. ✓
- Friction. ✓

**(Any 2 x 1)** (2)

10.2 **Power driven guillotine:**

- Test for correct operation. ✓
- Check that all guards are in place and operational. ✓
- Check if operating instructions are displayed. ✓
- Ensure that ancillary equipment is closely located. ✓
- Check if appropriate PPE is kept close by. ✓
- Check if housekeeping equipment is readily available. ✓
- Ensure that the guillotine is properly secured to the floor. ✓
- Tighten loose nuts and bolts. ✓
- Lubricate the machine adequately. ✓
- Clean the machine. ✓

**(Any 4 x 1)** (4)

10.3 **Failure of rollers:**

- Worn or damaged bearings. ✓
- Misalignment. ✓
- Contamination. ✓
- Excessive load. ✓
- Inadequate lubrication. ✓

**(Any 2 x 1)** (2)  
**[8]**



**QUESTION 11: TERMINOLOGY (DEVELOPMENT) (SPECIFIC)**

11.1 Square ✓ to round. ✓ (2)

11.2 **Cone:**

11.2.1 **Type of cone:**

- Conical frustrum ✓
- Truncated cone ✓

(Any 1 x 1) (1)

11.2.2 **Conical frustrum:**

- A – Vertical height ✓
- B – Top radius/Small radius ✓
- C – Slant height ✓
- D – Base radius/Large radius ✓

(4)

11.3 **Hopper:**

11.3.1 **A-1**

$$\begin{aligned} A-1 &= \sqrt{480^2 + 700^2 + 700^2} \\ &= \sqrt{230400 + 490000 + 490000} \\ &= \sqrt{1210400} \checkmark \\ &= 1100,18 \text{ mm } \checkmark \end{aligned}$$

(5)

11.3.2 **C-3**

$$\begin{aligned} C-3 &= \sqrt{250^2 + 120^2 + 700^2} \\ &= \sqrt{62500 + 14400 + 490000} \\ &= \sqrt{566900} \checkmark \\ &= 752,93 \text{ mm } \checkmark \end{aligned}$$

(5)

11.3.3 **X<sub>1</sub>-X<sub>2</sub>**

$$\begin{aligned} X_1 - X_2 &= \sqrt{480^2 + 700^2} \\ &= \sqrt{230400 + 490000} \\ &= \sqrt{720400} \checkmark \\ &= 848,76 \text{ mm } \checkmark \end{aligned}$$

(4)

[21]

**TOTAL: [200]**